
IN THE DRAWINGS


In Figs. 5-11, members 6, 7, 9, 8, 7, 10 and 6, respectively, were originally shaded to indicate heating. On the attached replacement sheets of these Figs. the shading is replaced zig-zag phantom lines that may suggest heating by zig-zag resemblance to electrical resistance but do not introduce such electrical resistance because in phantom lines.

In Figs. 9-11, more familiar liquid-indicating shading is used for ink 14.






2/5



4/5



FIG. 10



5/5

